


IMPROVEMENTS ON THE
 OCEAN CLEANUP SYSTEM
 BY ERIK VAN VLIET
 0630264550



CABLES FOR KEEPING
 THE PACMAN SYSTEM
 IN RIGHT U SHAPE




BUOYANCY
 ADDED

SIDE VIEW

BUOYANCY
 ADDED

WEIGHT
 ADDED

RETRACTABLE
 PARACHUTE ADDED
 FOR RIGHT VELOCITY




STRAIGHT ANCHOR LINE
 GIVES HIGH LOADS ON
 FLOATING SYSTEM

ROTATION OF MAIN
 TUBE DUE TO SIDE
 BUOYANCY FLOATERS

FLOATING ANCHOR
 IN THE DEEP

SHORT SIDE BUOYANCY
 PIPES GIVE TORSION
 IN MAIN PIPE



PLASTIC FOIL HANGING
 IN WATER

LET SIDE FLOATERS
 ROTATE MORE EASY
 AROUND MAIN PIPE
 USE ELASTIC ROPES
 FOR CONNECTION

DO YOU NEED A CLEVER CONCEPT OR IMPROVE IT
 CONTACT PRACTICAL SOLUTION TEL:0630264550
 INFO@PRACTICALSOLUTION.EU
 WWW.PRACTICALSOLUTION.EU/BUSINESS OR/ZAKELIJK